

Access Statements

Wingerworth Library. There is level access to the building and an accessible toilet in the building, there are doors into the building which are not automatic. The library itself is all on one level and there is a videophone, a hearing loop and the IT facilities have adaptive technology. Some adaptations have been made to the library and further reasonable adjustments need to be identified.

Whaley Bridge Library. The library is in the basement accessed by a flight of stairs and a very narrow passage. There are no automatic doors and no accessible toilet available. There are steps inside the library, there is a videophone and the IT facilities have adaptive technology. Some adaptations have been made to the library and further reasonable adjustments need to be identified.

Hadfield Library. There are shallow steps with a handrail to access the building from the outside, there are no automatic doors or accessible toilet. There is a videophone and the IT facilities have adaptive technology. Some adaptations have been made to the library and further reasonable adjustments need to be identified.

Glossop Library. The access to the building is not level and there are no automatic doors or accessible toilet. There is level access within the library itself and there is a videophone and the IT facilities have adaptive technology. Some adaptations have been made to the library and further reasonable adjustments need to be identified.

Matlock Library. There is access to the building from the outside via a slight ramp, but there are no automatic doors, no accessible toilet and the fire exits have steps. There is limited space within the library itself and any ramps to different areas are steep. There is a hearing loop, a videophone and the IT facilities have adaptive technology. Some adaptations have been made to the library and further reasonable adjustments need to be identified.

Belper Library. There is access to the building from the outside via a slight ramp, but there are no automatic doors, no accessible toilet and the fire exits have steps. There is limited space within the library itself and steep stairs to the first floor. There is a hearing loop, a videophone and the IT facilities have adaptive technology. Some adaptations have been made to the library and further reasonable adjustments need to be identified. Capital funding has been approved for a new library in Belper subject to the location of an appropriate site.