

**DERBYSHIRE COUNTY COUNCIL**

**CABINET MEETING**

**30 July 2013**

Report of the Acting Strategic Director – Environmental Services

**ADDITIONAL HIGHWAY WORKS RESULTING FROM SEVERE WEATHER CONDITIONS**

(1) **Purpose of the Report** To recommend to Cabinet a programme of works to address damage to the highway as a result of severe weather conditions.

(2) **Information and Analysis** Central Government has allocated £4 million to Derbyshire to address the damage caused to the highway as a result of both flooding and winter conditions. The finance is split between two financial years with £2.625m during the current year with the remainder allocated to next year. It is a condition of the finance that the programme is published by the County Council.

Cabinet Members will have noticed that the condition of the roads network deteriorated markedly last year following an unusually wet summer followed by periods of snow and frost. Many roads and footways suffered potholes to such an extent that keeping pace with the repairs became a major challenge.

In order to address this issue, specialist machinery was hired in at the end of the last financial year. However, the late and severe snowfall delayed that effort such that much of the remedial works were undertaken during the current financial year. Some £500,000 has therefore already been allocated from the available funding. Whilst the specialist machinery did an effective and economic job, much remains to be undertaken to bring the network back to a condition similar to that which existed before last year.

In order to address the issues of greatest concern to the public, County Councillors have been consulted and have given numerous locations where works are desirable. The extent of the requested works range from localised defects, which can be addressed by simple patching, to major resurfacing. Each request has been inspected and assessed for need and to determine if it meets the criteria for funding from the Government grant, which requires that works should not be part of a programme already planned and should seek to improve the resilience of the roads network.

The list attached as an appendix draws on a number of maintenance techniques including minor hand patching, machine patching, surface dressing and resurfacing. Where surface dressing is recommended, the road will be pre-patched during the current year with surface dressing being undertaken next year as a commitment against the 2014/15 funding.

It has not been possible to include all the requests submitted by Members in the suggested programme. However, where these have not been recommended, they will be held on file and considered as part of future works programmes or,, in the case of very minor works, funded from the maintenance revenue budget.

(3) **Financial Considerations** The schemes listed in the attached appendix will be fully funded from the additional central Government allocation for repairs to damage caused by severe weather conditions.

In preparing this report the relevance of the following factors has been considered: legal, prevention of crime and disorder, equality and diversity, human resources, environmental, health, property and transport considerations.

(4) **Key Decision** No.

(5) **Call-In** Is it required that call-in be waived in respect of the decisions proposed in the report? No.

(6) **Background Papers** None. Office contact details – Neil Hickman, extension 38550.

(7) **OFFICER'S RECOMMENDATIONS** That Cabinet:

- 7.1 Approves the list of works set out in the appendix as those to be undertaken and funded from the Government grant for remedial works resulting from severe weather conditions.
- 7.2 Notes that £500,000 has already been spent on the hire of specialist machinery to address the condition of the highway network at the start of the financial year.
- 7.3 Approves the publication of the programme on the County Council's website as required by the conditions of the grant.

**Mike Ashworth**  
**Acting Strategic Director – Environmental Services**

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
A	Alfreton	B600 Nott'm Road (Flowery Lees Lane to Victoria St)	Carriageway	Alfreton & Somercotes	SMA bed. Crazed, potholes, uneven, rutted.	Plane and resurface carriageway	£40,000	£0
A	Ashbourne	A515 St John's Street	Re-paving	Ashbourne	Cracked uneven PCC slabs	F'way R&R	45,000	0
A	Ashbourne	Moor Farm Road West	Carriageway	Ashbourne	AC fretting/stripping, isolated structural failure	Patch & Surface Dress 2014	5,000	10,000
A	Aston	Derby Road/Weston Road (upto Village Shop)	Carriageway	Aston	SD delaminating/isolated potholes	C'way R&R	19,000	0
A	Aston	Manor Farm Road/Moor Lane	Carriageway	Aston	AC potholed	Machine Patching	6,000	0
A	Barlborough	New Road	Carriageway	Barlborough & Clowne	Crazing/potholes - half width patch (between 2A and 22A)	PPSD (this year) damaged area and put on surface dressing programme for 2014	£3,500	£7,000
A	Baslow	Eaton Drive (Eaton Hill to "Charnwood")	Carriageway	Derwent Valley	AC fretting/oxidisation/potholes	Machine Patching	3,000	0
A	Belper	A609 Spencer Road	Carriageway	Belper	SD stripping & SMA cracking & potholing	Patch & Surface Dress 2014	4,000	12,000
A	Belper	John o' Gaunts Way	Carriageway	Belper	SMA recent patching done & SD stripping/delaminating/potholes	Patch & Surface Dress 2014	5,000	23,000
A	Bolsover	Castle Street	Carriageway	Bolsover South	Very poor condition, potholes, stripping.	Plane and resurface carriageway	£40,000	£0
A	Borrowash	Manor Road	Footway	Breaston	AC oxidising/cracking/isolated structural failure	F'way R&R	38,000	0
A	Borrowash	Charnwood Avenue	Footway	Breaston	AC structural failure/stripping surface course; PCC slabs uneven	F'way R&R	23,000	0
A	Boythorpe	Summerfield Road	Carriageway	Spire	Surface dressed (stripping), many potholes, very poor condition	Plane and resurface carriageway	£30,000	£0
A	Boythorpe	Walton Crescent	Footway	Boythorpe & Brampton South	Footway pothole and damaged edging o/s No. 31	F'way patch required	£2,000	£0
A	Boythorpe	Hunloke Avenue	Footway	Boythorpe & Brampton South	North side (from Boythorpe Rd to No.5). Uneven, potholes, crazed	F'way patch required	£2,000	£0
A	Brampton	Goytside Road	Carriageway	Boythorpe & Brampton South	Potholes at jtn with Factory St, poor condition	C'way patch required. Potholes reported to RRT (SBS 851555)	£5,000	£0
A	Brampton	Old Road	Carriageway	Boythorpe & Brampton South	Failed section (20m long x 1/2 c'way width) at jtn with St. Thomas St + section near bus-stop.	C'way patch required	£5,000	£0
A	Brimington	Princess Street	Carriageway	Brimington	Poor condition at jtn with Burrell St, potholes and crazing on rest of street	PPSD (this year) damaged area and put on surface dressing programme for 2014 (low priority)	£1,000	£5,000
A	Brimington	Hill View Road & Rayleigh Av	Carriageway	Brimington	Footway spalling in places, patches & reinstatements, uneven.	Add to footway slurry seal programme 2014 (high priority)	£0	£10,000
A	Brimington	Station Road	Carriageway	Brimington	Jtn of Bank Street very poor, full of potholes.	C'way patch required	£5,000	£0
A	Buxton	Victoria Park Road	Carriageway	Buxton North & East	Potholes and crazed. Including speed hump (plateau).	20m long c'way patch required o/s Sure Start to jtn with Boarstones Lane	£5,000	£0

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
A	Buxton	Ashwood Avenue	Carriageway	Buxton North & East	Surface dressed, full of potholes, poor condition.	Add to surface dressing programme 2014 (high priority)	£1,000	£3,000
A	Church Gresley	Albert Road	Carriageway	Swadlincote South	SD delaminating (shallow potholes)	Pothole & Surface Dress	0	3,000
A	Church Gresley	Gresleywood Road (in part)	Carriageway	Swadlincote South	SD delaminating (shallow potholes)	Pothole & Surface Dress	0	16,000
A	Church Gresley	George Street	Carriageway	Swadlincote South	HRA cracking/crazing and SD fretting with old SU trenches failing	Patch & Surface Dress 2014	4,000	12,000
A	Codnor	Redmoor Close	Carriageway	Ripley East & Codnor	SD stripping	Surface dressing 2014	0	1,500
A	Creswell	Elmton Road	Carriageway	Bolsover North	Poor reinstatement, uneven, patch	20m long x half c'way width patch (Speed hump to Gypsy Lane)	£5,000	£0
A	Danesmoor	Flaxpiece Road (Cemetery Road to one-way section)	Carriageway	Clay Cross South	Surface dressed, very poor condition, full of potholes/stipping.	Plane and resurface carriageway (include patch at jtn of Commonpiece Road and Thanet St)	£30,000	£0
A	Darley Dale	Grove Lane	Carriageway	Derwent Valley	Uneven, SD trenches, potholing - PPSD/SD	Patch & Surface Dress 2014	4,000	8,000
A	Denby	B6179 Derby Road (Flamstead School)	Carriageway Drainage	Horsley	Surface water issues from verge and onto carriageway	Drainage investigation & remedials	15,000	0
A	Denby	Hearnor Road (No. 10 to PC boundary @ Grammer Street)	Carriageway	Horsley	SMA, Isolated structural failure	Machine patching & Surface Dressing 2014	15,000	11,000
A	Drakelow	Drakelow Park at left turn for Walton on Trent and left for Drakelow	Carriageway	Linton	HRA rugous, fretting, isolated structural failure	Machine Patching	10,000	0
A	Draycott	Elvaston Street	Footway	Breaston	AC oxidising	F/way Slurry Seal 2014	0	3,000
A	Dunston	Cartmel Crescent	Carriageway	St. Mary's	Surface dressed, poor condition , many potholes, patches, reinstatements	Plane and resurface carriageway	£35,000	£0
A	Furness Vale	A6 (through village)	Footway	Whaley Bridge	Reinstatement through footway, slightly uneven, fretting at kerblne. From Yeadsley Lane to Bridgemont)	Add to footway slurry seal programme 2014 (high priority)	£0	£10,000
A	Glapwell	A617 (Young Vanish X'Roads)	Carriageway	Tibshelf	HFST - Crazed, potholes, rutting	Plane and resurface from Rowthorne Lane to Applecroft Close	£60,000	£0
A	Glossop	Arundel St/Fauvell Road	Carriageway	Glossop & Charlesworth	Old surface dressing bed. Potholes, crazing, reinstatement.	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority)	£5,000	£13,000
A	Grangewood	Rushen Mount	Carriageway	Birdholme	Surface dressed, potholes, spalling, po	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority)	£1,500	£4,000
A	Grangewood	St Augustines Avenue (St Augustines Rd to Baden Powell Road)	Carriageway	Birdholme	SMA bed, some potholes, needs sealing	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority)	£3,000	£10,000
A	Hadfield	Chapel Lane/Ridings Road lower junction	Carriageway	Etherow	Surface dressing bed with potholed SU trench	C/way patch at junction	£5,000	£0

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
A	Hasland	Smithfield Avenue	Footway	Birdholme	Generally OK, Some patches & reinstatements, needs sealing	Put on slurry sealing list	£0	£5,000
A	Heage	Over Lane/Boothgate	carriageway	Belper	SD isolated structural failure. Much recent patching	Patch & Surface Dress 2014	5,000	18,000
A	Heanor	Holmes Street	Carriageway	Heanor Central	SD, potholes & uneven	C/way R&R	19,000	0
A	Heanor	John Street	Carriageway	Heanor Central	SD low texture	Patch & Surface Dress 2014	1,500	3,500
A	Heanor	Stainsby Avenue	Carriageway	Heanor Central	SD mainly sound, drainage issue half way down.	Solve drge problem & machine patch	10,000	0
A	Heanor	Leniscar Avenue	Footway	Heanor Central	AC delaminating/cracking/structural failure (overrun)	F/way R&R	35,000	0
A	Heanor	Brook Street	Footway	Heanor Central	AC delaminating/cracking (overrun)	F/way R&R	33,000	0
A	Heanor	Grace Crescent	Carriageway	Heanor Central	SD delaminating and isolated structural failure	Patch & Surface Dress 2014	1,000	3,000
A	Ilkeston	Cotmanhay Road	Carriageway	Ilkeston East	various, structural failure uneven	Machine Patching	45,000	0
A	Ilkeston	Station Road (Alvenor Street to Rupert Street)	Footway	Ilkeston East	Delaminating S/C	F/way R&R	20,000	0
A	Ilkeston	St John's Road/Kensington Gardens junct	Carriageway	Ilkeston South	SD, potholes/cracking	Machine Patching	6,000	0
A	Ilkeston	Longfield Lane (Garden Avenue to Corporation Road)	Carriageway	Ilkeston South	SD isolated structural failure	Patch & Surface Dress 2014	3,000	12,000
A	Ilkeston	Orchard Street junct Nottingham Road	Carriageway	Ilkeston South	SMA cracking/crazed	Surface dressing 2014	0	10,000
A	Ilkeston	Westwick Street/Charles Close	Carriageway	Ilkeston South	SD isolated stripping	Surface dressing 2014	3,000	3,000
A	Ironville	Coach Road	Carriageway	Alfreton & Somercotes	Existing surface dressing, stripping in p	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority)	£10,000	£30,000
A	Kilburn	Rowan Drive junct Ryknield Road	Carriageway	Horsley	SD potholes, isolated structural failure	Machine Patching	5,000	0
A	Kilburn	Ryknield Road (Chapel Street to Ticknall Lane)	Carriageway	Horsley	SD - Isolated structural failure	Patch & Surface Dress 2014	1,500	3,500
A	Kilburn	Horsley Road (Large potholes in various locations)	Carriageway	Horsley	SD - Isolated structural failure	Patch & Surface Dress 2014	6,000	19,000
A	Killamarsh	Norwood Crescent	Carriageway	Eckington & Killamarsh	Surface dressed concrete road. Poor ride quality. Failed at joints. Potholes.	Plane and resurface carriageway (including crack & seat)	£25,000	£0
A	Killamarsh	Bridge Street & High Street	Carriageway	Eckington & Killamarsh	Poor condition, reinstatements & patches	Plane and resurface carriageway (from Sheffield Road to Sheepcote Road)	£55,000	£0
A	Kirk Hallam	St Norbert's Drive	Carriageway	Ilkeston South	SD on concrete: delamination, uneven, isolated structural failure	Patch & Surface Dress 2014	20,000	25,000
A	Kirk Hallam	Wirksworth Road	Carriageway	Ilkeston South	SD on concrete: delamination, uneven, isolated structural failure	Patch & Surface Dress 2014	13,000	22,000

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
A	Langley Mill	Turton Close	Footway	Greater Heanor	AC oxidising, structural failure due to overrun	F/way R&R	10,000	0
A	Linton	Main Street/Hillside Road junction	Carriageway	Linton	SD stripping/fretting	Machine Patching	8,000	0
A	Linton	Road adj. Coton Park coal stocking yard	Carriageway	Linton	SD isolated potholing	C/way Patching	4,000	0
A	Long Eaton	Briar Gate (footways high no's to Wilsthorpe School) to Bracken Road	Footway	Petersham	PCC slabs - very uneven	F/way R&R	44,000	0
A	Long Eaton	Cranmer Street	Carriageway	Long Eaton	SD uneven, SU transverse crossings	Machine Patching	17,000	0
A	Long Eaton	Collingwood Road o/s No. 3 (Poor Surface on dropped kerb, uneven slabs & uneven kerbstone)	Footway	Long Eaton	Existing concrete Vehicular Crossings cracking/spalling	Patching	1,000	0
A	Long Eaton	Cedar Avenue (25yards LHS near smal business unit. Poor quality dropped kerb)	Footway	Long Eaton	Existing concrete Vehicular Crossings cracking/spalling	Patching	1,000	0
A	Loscoe	Clarke Avenue spring	Drainage	Heanor Central	SD cracking, isolated pothole repairs	Solve drge problem & machine patch	5,000	0
A	Lower Kilburn	B6179 Lower Kilburn (midde of road has sunk following resurfacing)	Carriageway	Horsley	Sunken construction joints under SD	Joint treatment/patch	11,000	0
A	Marlpool	Buxton Green	Carriageway	Greater Heanor	SD uneven	Patching	12,000	0
A	Matlock	Cavendish Road	Carriageway	Matlock	SD Isolated structural failure/potholes	Patch & Surface Dress 2014	4,000	13,000
A	Matlock	Chesterfield Road (Wellington Street to Slack Hill)	Carriageway	Matlock	SMA Isolated structural failure/potholes	Machine Patching & SD	15,000	65,000
A	Matlock	Chesterfield Road (Wellington Street to Smedley Street East)	Carriageway	Matlock	SMA structural failure/potholes	C/way R&R	0	110,000
A	Melbourne	Derby Road/Penn Lane junction	Carriageway	Melbourne	SD Cracking and uneven	Machine Patching	5,000	0
A	Middlecroft	Fern Avenue	Carriageway	Staveley	SD joint failure	Joint repairs & Surface dressing 2014	20,000	5,000
A	New Mills	Longlands Road	Carriageway	New Mills	Failed surface dressing, very poor, lots of potholes.	Plane and resurface carriageway (from Hague Bar Road to Hall St + jtn of Hall St)	£32,000	£0
A	New Mills	Hall Street	Carriageway	New Mills	Surface dressed, stripping, crazed, potholes, poor	Plane and resurface carriageway (from Market Street to Aldersgate)	£15,000	£0
A	Newhall	High Street (Wellwood Road x-roads to Beards Road)	Carriageway	Swadlincote North	SD stripping & rugous, isolated structural failure	Patch & Surface Dress 2014	9,000	16,000
A	Newhall	Pingle Farm Road	Carriageway	Swadlincote North	SD delaminating (shallow potholes)	Pothole & Surface Dress 2014	1,500	3,500
A	Newhall	Robinson Road	Carriageway	Swadlincote North	un-SD section is delaminating	Machine Patching	5,000	0
A	Newhall	Orchard Street	Carriageway	Swadlincote North	Thin AC/SD uneven isolated structural failure	Patch & Surface Dress 2014	3,000	6,000
A	Newhall	Birch Avenue	Carriageway	Swadlincote North	SD delaminating	Patch & Surface Dress 2014	3,000	9,000
A	North Wingfield	Bamford Avenue	Carriageway	Clay Cross South	Poor condition (potholes) at jtn with New Street	C'way patch required at jtn with New Street	£5,000	£0

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
A	Palterton	Rylah Hill	Carriageway	Bolsover South	Poor condition (potholes and reinstatement) at jtn with Main Street	C'way patch required at jtn with Main Street	£5,000	£0
A	Pilsley	Lansbury Avenue	Carriageway	Clay Cross South	Old surface dressing bed, small potholes, stripping. Poor condition (Morton Road to Queensway)	Plane and resurface carriageway	£8,000	£0
A	Pilsley	Queensway	Carriageway	Clay Cross South	Surface dressed, stripping in places	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority)	£2,000	£6,000
A	Pilsley	Queensway & Broom Avenue	Footway	Clay Cross South	Surface spalled, uneven, potholes, verges in poor condition.	Excavate and reconstruct footway, repair damaged verges	£80,000	£0
A	Pilsley	Pear Tree Road	Carriageway	Clay Cross South	Surface dressed, small potholes, generally OK	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority) Pothole reported to RRT (SBS 851546)	£1,000	£4,000
A	Pilsley	Prospect Road	Carriageway	Clay Cross South	Surface dressed, old reinstatements, patches, small potholes	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority).	£1,000	£2,000
A	Pinxton	Elm Close	Carriageway	South Normanton & Pinxton	Surface dressed, potholes filled, generally OK	C'way patch required o/s No.4	£5,000	£0
A	Pinxton	Wilson Street	Footway	South Normanton & Pinxton	3 damaged kerbs o/s garage	Replace kerbs	£500	£0
A	Repton	Springfield Road	Carriageway	Repton & Etwall	SD on concrete - delaminating/cracking	C/way R&R	58,000	0
A	Ripley	Ash Crescent/Woodside Avenue junct	Carriageway	Ripley West	SD potholed/uneven	Patching	4,000	0
A	Ripley	Ash Crescent	Carriageway	Ripley West	SD stripping/potholed	Patching	10,000	0
A	Ripley	Hawthorn Avenue	Carriageway	Ripley West	SD/concrete road - Cracking/crazing, Isolated structural failure	C/way R&R	40,000	0
A	Ripley	Pear Tree Avenue	Carriageway	Ripley West	SD - isolated structural failure/isolated potholes	Patch & Surface Dress 2014	4,000	7,000
A	Ripley	A610/A38 Rd bt rut between A610 Butterley by-Pass and A38 SB slip on	Carriageway	Ripley West	Thin surface fretting & centre joints failing	C/way R&R	0	90,000
A	Ripley	Park Avenue & Reynold Avenue	Carriageway	Ripley East & Codnor	SD on concrete, cracking fretting	C/way R&R	26,000	0
A	Ripley	Alfred Street (Nottingham Road to Havelock Street)	Carriageway	Ripley East & Codnor	SD potholing	Patch & Surface Dress 2014	3,000	6,000
A	Ripley	Booth Street	Carriageway	Ripley East & Codnor	SD long section of structural failure	Patching	5,000	0
A	Ripley	Crossley Street	Carriageway	Ripley East & Codnor	SD isolated structural failure	Patching	5,000	0
A	Sawley	Ladylea Road	Footway	Sawley	PCC slabs, cracked/uneven	F/way R&R	12,000	0
A	Sawley	Elvaston drive	Footway	Sawley	PCC slabs, cracked/uneven	F/way R&R	29,000	0
A	Sawley	Shirley street	Footway	Sawley	PCC slabs, cracked/uneven	F/way R&R	20,000	0

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
A	Shardlow	B5010 London Road (Ambaston Lane to Canal Bridge)	Carriageway	Aston	HRA Rugous with SU trenches	Machine Patching	30,000	0
A	Shardlow	B5010 London Road (Shardlow village/Navigation Inn to Cavendish Bridge)	Carriageway	Aston	HRA Rugous, fretting, isolated structural failure	C'way R&R	105,000	0
A	Shirebrook	Ashbourne Street	Carriageway	Shirebrook & Pleasley	SMA bed, generally OK. Potholes in jtn with Main St and access to car park	C'way patch required in jtn. PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority)	£1,000	£3,000
A	Shirebrook	Station Road (Portland Rd to Ashbourne St)	Carriageway	Shirebrook & Pleasley	Surface dressed, many patches & reinstatements.	Add to surface dressing programme 2014 (high priority)	£4,000	£16,000
A	Shirebrook	Little Lane	Carriageway	Shirebrook & Pleasley	Junction with Main Rd poor, full of potholes	C'way patch required	£5,000	£0
A	Shirebrook	Byron Street	Carriageway	Shirebrook & Pleasley	Junction with Main Rd poor, full of potholes. Rest of road is SMA, crazing & reinstatements	C'way patch required in jtn. PPSD (this year) damaged areas and put on surface dressing programme for 2014 (high priority)	£1,000	£3,000
A	Smalley	Adale Road	Carriageway	Horsley	C'way - SD potholing/cracking	Patch & Surface Dress 2014	3,000	2,000
A	Smalley	Kerry Drive/Dix Avenue (various sections)	Carriageway	Horsley	SD - Isolated structural failure	Patch & Surface Dress 2014	8,000	10,000
A	Somercotes	B600 Tiger P.H. to R'bout	Carriageway	Alfreton & Somercotes	Crazed, rutted, potholes, poor condition	Plane and resurface carriageway	£60,000	£0
A	South Normanton	Bright St (Market St to No.10)	Carriageway	South Normanton & Pinxton	Poor condition. Potholes, crazed, uneven.	PPSD (this year) damaged area and put on surface dressing programme for 2014 (high priority)	£500	£1,000
A	South Normanton	Water Lane	Carriageway	South Normanton & Pinxton	Surface dressed, generally OK, junction poor.	C'way patch required at jtn with South St.	£5,000	
A	Stanfree	Clowne Road	Carriageway	Barlborough & Clowne	Old surface dressing bed - Potholes, chipping loss, uneven.	Plane and resurface from No.81 to No.74	£70,000	£0
A	Staveley	Hall Lane (A619 to Library)	Carriageway	Staveley North & Whittington	Potholes, crazing, poor condition. Old SMA bed	Plane and resurface carriageway	£15,000	£0
A	Swadlincote	Davis Road	Carriageway	Swadlincote Central	SD Perished, delamination	C'way R&R	19,000	0
A	Swadlincote	Springfield Road (potholes)	Carriageway	Swadlincote Central	SD Isolated potholes, some patching done	Surface Dress 2014	0	14,000
A	Tupton	Ankerbold Road	Carriageway	Clay Cross North	Jtn with Queen Victoria Road, Tupton Moor Close and Pond Lane. Many potholes.	3 areas require c'way patching	£15,000	£0
A	Tupton	Redfern Street	Carriageway	Clay Cross North	Wingfield Road to Ford St. Concrete road with overlay. Joint failure, potholes and crazing.	Plane, crack & seat and resurface	£10,000	£0
A	Unstone	Crow Lane (Main Road to river)	Carriageway	Dronfield East	Potholes, crazing, poor condition. Old SMA bed	Plane and resurface carriageway	£20,000	£0
A	West Hallam	Hallam Way	Footway	Breadsall & West Hallam	AC Oxidising footway	F'way Slurry Seal 2014	0	17,000



Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
A	Whaley Thorns	Main Street	Carriageway	Bolsover South	Very poor, many potholes, uneven	Plane and resurface half c'way width from North St to Medical Centre, plateau at Jellicoe St and jtn with Portland Street	£15,000	£0
A	Wirksworth	Summer Lane/Yokecliffe Drive	carriageway	Wirksworth	SD delaminating and isolated structural failure	Machine Patching	2,000	0
B	Alfreton	Ley Gardens & Avenue	Footway	Alfreton & Somercotes	Patches, uneven, generally OK	Put on slurry sealing list	£0	£3,000
B	Alfreton	Flowery Lees Lane	Carriageway	Alfreton & Somercotes	Surface dressed, some potholes, crazing, uneven	On surface dressing rolling programme	£2,000	£10,000
B	Alfreton	Chatham Avenue	Carriageway	Alfreton & Somercotes	Surface dressed, some potholes, crazing, uneven	On surface dressing rolling programme	£0	£1,000
B	Alfreton	Henry Crescent	Carriageway	Alfreton & Somercotes	Surface dressed, some potholes, crazing, uneven	On surface dressing rolling programme	£0	£1,000
B	Alfreton	Preston Avenue	Carriageway	Alfreton & Somercotes	Surface dressed, some potholes, crazing, uneven	On surface dressing rolling programme	£0	£7,000
B	Alfreton	Victoria Street	Carriageway	Alfreton & Somercotes	Surface dressed, some potholes, crazing, uneven	On surface dressing rolling programme	£0	£1,500
B	Aston	Willowpark Way/Weston Road	Carriageway	Aston	SMA in junction bellmouth potholing	Machine Patching	2,000	0
B	Barlborough	Clowne Road	Carriageway	Barlborough & Clowne	Old HRA bed - Uneven, potholes, failed reinstatements	Plane and resurface from De Rhodes R'bout to No.87	£75,000	£0
B	Belper	Whitemoor Lane (town end)	carriageway	Belper	SD stripping and isolated structural failure	Patch & Surface Dress 2014	3,000	6,000
B	Borrowash	Derwent Avenue	Footway	Breaston	AC uneven, isolated structural failure	F/way Slurry Seal 2014	0	2,000
B	Brampton	Barker Lane	Carriageway	Boythorpe & Brampton South	Some patches, filled potholes, not bad condition	Add to surface dressing programme 2014 (medium priority).	£2,000	£10,000
B	Breaston	Shirley Crescent (o/s 12 to 18)	Footway	Breaston	AC oxidising, fretting, isolated structural failure	F/way Patching	3,000	0
B	Breaston	Stevens Lane (o/s 78 to 80; o/s 89 to 101; o/s 121)	Footway	Breaston	AC cracking delaminating	F/way Patching	6,000	0
B	Brimington	Station Road	Footway	Brimington	O/S shops, patches, potholes, reinstatement	F'way patch required	£2,000	£0
B	Castle Gresley	A444 Home Farm Court - Pothole	Carriageway	Linton	SMA potholing	Machine Patching	7,000	0
B	Denby	High Bank (Bulls Head to surfacing joint)	Footway	Horsley	AC oxidising surface	F/way Slurry Seal 2014	0	2,000
B	Denby	Breach Road	Footway	Horsley	AC uneven sections	Patch & slurry seal 2014	3,000	7,000
B	Draycott	Derby Road (adj. New Street)	Footway	Breaston	F/way SD delamination	F/way Patching	1,000	0
B	Dronfield	Sainsbury's R'bout	Carriageway	Dronfield East	HRA bed, signs of potholing/crazing	Plane and resurface carriageway	£15,000	£0
B	Dronfield	Gosforth Lane/High Street R'bout	Carriageway	Dronfield East	Small area of crazing.	C'way patch required	£5,000	£0
B	Dronfield	Scarsdale Road/Wilson St	Carriageway	Dronfield East	Potholes in junction	C'way patch required	£5,000	£0
B	Duffield	A6 Milford Road	Carriageway	Duffield & Belper South	HRA, uneven RE's, cracking & Crazing	Machine Patching	15,000	0

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
B	Holmgate	Meadow Road	Carriageway	Clay Cross North	Surface dressed, jtn's in poor condition. Potholes.	C'way patch jtn's with Mill Lane and North Road. Report potholes to RRT (SBS 851529)	£10,000	£0
B	Holmgate	Cromford Road	Carriageway	Clay Cross North	Surface dressed, generally OK. One patch required between North Road and Ashbourne Road	C'way patch required.	£5,000	£0
B	Holmgate	Holmgate Road	Carriageway	Clay Cross North	Surface dressed, starting to fail in places. 2 no. potholes.	Add to surface dressing programme for 2014. Report potholes o/s school to RRT (SBS 851527)	£3,000	£18,000
B	Horsley	Church Street/Lady Lea Road/Smalley Mill Road	Carriageway	Horsley	SD uneven Isolated structural failure (Smalley Mill Rd SD 2012 & perfect - no works planned)	Patch & Surface Dress 2014	5,000	25,000
B	Horsley Woodhouse	Clement Road (pothole & loose kerb stones)	Footway	Horsley	F'way - Oxidising AC but sound	F'way Slurry Seal 2014	0	12,000
B	Hulland Ward	A517 Main Road (Hulland Garage to Viewdales Close and onto Charles Walker Close)	Footway	Ashbourne	AC isolated structural failure	F'way Slurry Seal 2014	0	15,000
B	Ilkeston	Ashdale Road/Greenwood Road junction	Carriageway	Ilkeston South	SD isolated structural failure	Patching	5,000	0
B	Killamarsh	Sheffield Road	Carriageway	Eckington & Killamarsh	Majority of road patched over last few years. One patch required between Stanley St and Bridge St. Odd pothole, poor reinstatement.	C'way patch required	£5,000	£0
B	King Sterndale	Road to King Sterndale	Carriageway	Buxton North & East	Surface dressed, recently jet patched.	Add to surface dressing programme 2014 (low priority)	£0	£20,000
B	Kirk Hallam	Windsor Crescent adj. Trent Road	Carriageway	Ilkeston South	SD delaminating (shallow potholes)	Patching	4,000	0
B	Melbourne	Queensway	Carriageway	Melbourne	SD Isolated structural failure/potholes	C'way Patching	4,000	0
B	Newhall	The Rise	Carriageway	Swadlincote Central	SD Isolated minor delamination	Pothole & Surface Dress	1,000	4,000
B	Pilsley	Rother Street	Carriageway	Clay Cross South	Surface dressed, very poor patches, uneven, potholes	Plane and resurface carriageway	£10,000	£0
B	Pilsley	Bridge St/Church St	Carriageway	Clay Cross South	Surface dressed, generally OK. Odd patch required.	PPSD (this year) damaged area and put on surface dressing programme for 2014 (medium priority)	£5,000	£20,000
B	Ripley	Field Terrace (Pear Tree PH to Ivy Grove)	Footway	Ripley West	SD - Isolated potholes, cracking/uneven	Patch & Surface Dress 2014	1,500	1,500
B	Ripley	Norman Road junctions of Dove Road to Derwent Road	Carriageway	Ripley West	SD potholing	Patch & Surface Dress 2014	1,500	2,000
B	Ripley	Wall Street	Carriageway	Ripley East & Codnor	SD uneven very narrow	Patch & Surface Dress 2014	0	4,000
B	Smalley	A608 Main Road (Rose & Crown to Smalley Hall)	Footway	Horsley	AC small length in 40mph section	F'way Patching	10,000	0

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
B	Smalley	Adale Road	Footway	Horsley	F/way - Oxidising fretting	Patch & slurry seal 2014	2,000	2,000
B	South Normanton	West Street	Carriageway	South Normanton & Pinxton	Old surface dressing bed.	PPSD (this year) damaged area and put on surface dressing programme for 2014 (medium priority)	£500	£1,000
B	South Normanton	Carr Lane	Carriageway	South Normanton & Pinxton	Surface dressed, patches & reinstatements	PPSD (this year) damaged area and put on surface dressing programme for 2014 (medium priority)	£1,000	£1,000
B	Spital	Valley Rd & Hartington Rd	Carriageway	Spire	Surface dressed, narrow, stripping, potholes, patches, poor condition.	Plane and resurface carriageway	£50,000	£0
B	Stonegravels	Higher Albert St	Carriageway	Spire	Surface dressing starting to craze, potholes in c'way	Add to surface dressing programme 2014 (medium priority). Potholes reported to RRT (SBS 851554)	£1,000	£6,000
B	Tupton	Davenport Road	Carriageway	Clay Cross North	Wingfield Road to Ford St. Concrete road with overlay. Joint failure, potholes and crazing. Not as bad as Redfern St	Plane, crack & seat and resurface.	£10,000	£0
B	West Hallam	St Wilfred's Road	Carriageway & some footways	Breadsall & West Hallam	SD structural failure on uphill lane	Patch	12,000	0
B	Whaley Common	Mag Lane	Carriageway	Bolsover South	Poor condition, small length (20m section) near jtn with Waley Common	C'way patch required	£5,000	£0
B	Wirksworth	Okerthorpe Road, Bolehill	carriageway	Wirksworth	Urban AC oxidising; Rural grass	Urban - add to Slurry Seal rolling programme; Rural nothing	0	7,000
C	Aldwark	Main Road	carriageway	Wirksworth	SD delaminating and potholes	Patch & Surface Dress 2014	5,000	25,000
C	Apperknowle	High Street	Carriageway	Dronfield East	Some potholes, minor crazing.	PPSD (this year) damaged area and put on surface dressing programme for 2014 (low priority).	£2,000	£8,000
C	Buxton	Cross Street	Carriageway	Buxton North & East	Surface dressed , OK condition	Add to surface dressing programme 2014 (low priority)	£0	£3,000
C	Buxton	Dakin Avenue	Carriageway	Buxton North & East	Surface dressed , OK condition	Add to surface dressing programme 2014 (low priority)	£0	£4,000
C	Creswell	Skinner Street	Carriageway	Bolsover North	Surface dressing bed - General OK. Small section with potholes/uneven	Patch required from Markland View to Elmton View	£5,000	£0
C	Duffield	A6 Flaxholme	Footway	Duffield & Belper South	Footway in sound condition Surface water flows from c/way onto footway and into properties?	Raise level of dropped kerbing	10,000	0
C	Glossop	Manor Park Road	Carriageway	Glossop & Charlesworth	Old surface dressing bed. No actionable defects.	Add to surface dressing programme 2014 (low priority)	£2,500	£10,000

Highway Maintenance Additional Severe Weather Budget  
Appendix

Priority	Parish	Location	Intervention Description	Electoral Division	Existing Condition	Proposed Treatment	2013/14	2014/15
C	Grassmoor	Chapman Lane	Carriageway	Sutton	Surface dressed - minor crazing, odd reinstatement, generally OK	Add to surface dressing programme	£1,000	£5,000
C	Heage	Bakers Hill	Carriageway	Ripley West	SD - uneven/potholes	Pothole & Surface Dress	1,500	3,500
C	Horsley	Horsley Road (adjacent village green) surfacing worn away	Carriageway	Horsley	SD low texture	Surface dressing 2014	0	2,000
C	Ilkeston	Birch Avenue (Pothole adj. No. 2)	Carriageway	Ilkeston South	SD delaminating (shallow pothole)	Surface dressing 2014	0	2,000
C	Newbold	Lucas Road	Carriageway	Loundsley Green & Newbold	Surface dressed. Generally OK, some chipping loss	Add to surface dressing programme 2014 (low priority)	£1,000	£9,000
C	South Normanton	Market Street	Carriageway	South Normanton & Pinxton	Surface dressed, uneven.	PPSD (this year) damaged area and put on surface dressing programme for 2014 (low priority).	£2,000	£10,000
C	South Normanton	Church Street	Carriageway	South Normanton & Pinxton	Surfce dressed, uneven	PPSD (this year) damaged area and put on surface dressing programme for 2014 (low priority).	£1,000	£4,000
C	South Normanton	Carter Lane East	Carriageway	South Normanton & Pinxton	Surface dressed, development on site.	On surface dressing rolling programme. Pothole reported to RRT (SBS 851554)	£5,000	£22,000
C	Stenson Fields	Grampian Way (Asda to Stenson Road: Junctions with Pilgrim's Way & Glencroft Drive; Pedestrian refuges; sunken manholes)	Carriageway	Aston	AC fretting isolated potholes	Patching	4,000	0
C	Various	Design Costs	Carriageway & Footway	Various	N/A	Various	29,000	0
C	Various	Various Locations Countywide	Carriageway & Footway Emergency	All	N/A	Proprietary Repair and Machine Patching	524,000	0
							2,625,000	1,020,500