

Year	Area ID	Area Name	Name of Location	Natural Grid Reference	Location Description	Start date	Days duration	Probability	Main cause of flooding	Additional causes of flooding	Confidence in main source of flooding	Main mechanism of flooding	Main mechanism of flooding	Significant consequences to human health	Human health consequences - residential properties	Property used method	Other human health consequences	Significant economic consequences	Number of non-residential properties flooded	Property used method	Other economic consequences	Significant consequences to the environment	Environmental consequences	Significant consequences to cultural heritage	Cultural heritage consequences	Persons	Date taken	Area Source	Flood event confidence	Flood event source	Survey date	Photo ID	Language	Archive data	Positive history descriptor	European Flood Data Code	
					Unlabelled flooding across county due to intense and prolonged rainfall. Approximately 1 month rainfall (50mm) in a day in late October. Further rainfall in early November led to saturated ground. Flood and surface water flooding. River Corwent and Betsu Brook banks. Road and rail transport network disrupted. Airfield roads in Chesterfield, Mallock and Bakersfield. Betsu Brook Hospital basement and Rowley CE School basement flooded. Army and coastal engineers protect approximately 200 homes in Heston. 20 houses flooded and 10 homes evacuated in Chesterfield. Thousands of sand bags used. Structural damage to 30 roads. 8 killed.			Unknown	Main rivers	Surface Runoff, Ordinary Watercourses		Medium	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0001
					24 houses flooded. 25 cars damaged.			Unknown	Surface runoff		Medium	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0002		
					1423 houses in Bakersfield flooded. Via Sella Brook burst banks causing ASOT2 to flood. Road water channel to business park to gravel tonnes. 48 cars damaged.			Unknown	Surface runoff	Ordinary Watercourses	Medium-Low	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0003		
					Widespread flooding in Glasgow due to flood and surface water flooding. Properties flooded and widespread disruption to transport network. A57 flooded along High Street Road, near a major deep railway.			Unknown	Main rivers	Surface Runoff	Medium	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0004		
					Unlabelled flooding across county due to intense and prolonged rainfall. River Wye and Corwent overflowing banks. 20 days evacuation. Property on arterial roads in Betsu, Darby Dale, Bakersfield and Biston. Betsu river gardens and Mallock West Road. More than half average monthly rainfall in two days.			Unknown	Main rivers	Surface Runoff	Medium-Low	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0005		
					Wye Wye overtopps banks following snow melt. Flooding in All Bakersfield to Biston.			Unknown	Main rivers	Surface Runoff	Medium-Low	Natural exceedance	Snow melt Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0006		
					Unlabelled flooding across county. Mallock, Linton, Corwent and Corwent Flooded in Chesterfield. Corwent Hill flooded, 10 1/2 houses. 10th. Ships on Casemary Lane, Mallock flooded. Road and rail disruption across county. Approximately 3000 cars parked.			Unknown	Main rivers	Surface Runoff	Medium	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0007		
					Flooding in Chesterfield, South Derbyshire and Ashby. Four major overtopps banks. A17 closed Hens Bridge to M1 Junction 20. Residential properties flooded in Chesterfield. Widespread disruption to road network across county. 2000 cars parked in 24 hours.			Unknown	Main rivers	Surface runoff	Medium	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0008		
					Number of flooding incidents to residential properties. 21 50mm rainfall.			Unknown	No data		Unknown	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0009		
					Unlabelled flooding across county. Betsu Brook Hospital flooded and over 100 residential properties. Widespread disruption to transport network. ASOT2 Long Betsu flooded.			Unknown	No data		Unknown	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0010		
					Houses flooded for second time in week in Betsu. 17 2 min rainfall.			Unknown	No data		Unknown	Natural exceedance	No data	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0011		
					10000 houses flooded after signs of quarry burst to banks. Approximately 30 homes flooded and A623 closed.			Unknown	Artificial infrastructure		Medium	Failure	Flash Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0012		
					Unlabelled flooding across county due to intense and prolonged rainfall. Flood and surface water flooding. Widespread disruption to road and rail transport network. Chesterfield and Corwent affected with residential properties and major roads flooded. River Corwent again further overtopped banks and hundreds of residents evacuated. River Corwent and Wye overtopps and several roads flooded in Mallock, Betsu, Betsu, Betsu. Betsu bridge treatment works threatened by water. A number of commercial buildings. Residential property flooding due to muddy causes involving a combination of surface Runoff, Ordinary Watercourses overflowing, drainage system overwhelmed or damaged and culvert obstruction. Commercial flooded Heston, Chesterfield and Heston and other damage. Agricultural losses of crops and livestock occurred in South Derbyshire.			Unknown	Main rivers	Surface Runoff, Ordinary Watercourses		Low	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0013	
					Flooding incidents in Derbyshire Dales and South Derbyshire. Flood damage to residential properties in Ashbourne and Parson. Egginton Millage cut off due to closure of A38. Sandbags provided in Hartshill. Damage to residential and commercial properties in Mallock. 100mm rainfall in 2 days.			Unknown	Main rivers	Surface Runoff, Ordinary Watercourses	Low	Natural exceedance	Natural Flood	No	Unknown	Unknown	Unknown	No	Unknown	Unknown	Unknown	No	Unknown	No	Unknown	Media / LA	Unknown	Unknown	Unknown	Unknown	Unknown	Media / LA	Unmarked	Unmarked	UKES000000P0014		